

WEST Search History

[Hide Items](#) [Restore](#) [Clear](#) [Cancel](#)

DATE: Thursday, September 29, 2005

<u>Hide?</u>	<u>Set Name</u>	<u>Query</u>	<u>Hit Count</u>
<i>DB=PGPB,USPT,USOC,EPAB,JPAB,DWPI; PLUR=YES; OP=OR</i>			
<input type="checkbox"/>	L33	l24 same shadow same mask	18
<input type="checkbox"/>	L32	l28 and 420/\$.ccls.	41
<input type="checkbox"/>	L31	l28 and 313/\$.ccls.	5
<input type="checkbox"/>	L30	l28 and 148/\$.ccls.	32
<input type="checkbox"/>	L29	L28 same etch\$3	4
<input checked="" type="checkbox"/>	L28	L25 same sulfide	588
<input type="checkbox"/>	L27	L25 same shadow same mask same sulfide	0
<input type="checkbox"/>	L26	L25 same shadow same mask	13
<input type="checkbox"/>	L25	L24 same (mns or cus or cu2s)	11007
<input type="checkbox"/>	L24	(iron or fe) same (ni or nickel) same (cu or copper) same (mn or manganese) same (s or sulfur)	18039
<input type="checkbox"/>	L23	l8 and 420/94.ccls.	51
<input type="checkbox"/>	L22	L20 and shadow and mask	12
<input type="checkbox"/>	L21	L20 and sulfide	29
<input type="checkbox"/>	L20	l8 and 148/336.ccls.	112
<input type="checkbox"/>	L19	l8 and (sulfide same etch\$3)	126
<input type="checkbox"/>	L18	L17 and 420/\$.ccls.	15
<input type="checkbox"/>	L17	L16 and ((iron or fe) near (ni or nickel) near alloy)	327
<input type="checkbox"/>	L16	L15 and etch\$3	3536
<input type="checkbox"/>	L15	l8 and ((mns) or (manganese near sulfide)) and (cus or (copper near sulfide))	33286
<input type="checkbox"/>	L14	L12 and (mns or (manganese near sulfide)) and (recrystallization or anneal\$3)	94
<input type="checkbox"/>	L13	L12 and (mns or (manganese near sulfide))	159
<input type="checkbox"/>	L12	L8 and (shadow near mask) and (cus or (copper near sulfide))	166
<input type="checkbox"/>	L11	L10 and sulfide	78
<input type="checkbox"/>	L10	L8 and (shadow near mask)	238
<input type="checkbox"/>	L9	L8 and(shadow near mask)	238
<input type="checkbox"/>	L8	(iron or fe) and (ni or nickel) and (cu or copper) and (mn or manganese) and (s or sulfur)	65561

DB=JPAB; PLUR=YES; OP=OR

<input type="checkbox"/>	L7	L6 same ((cu or copper) near sulfide)	2
<input type="checkbox"/>	L6	l3 same (sulfide)	81
<input checked="" type="checkbox"/>	L5	L3 same diameter same (iron near nickel)	0
<input checked="" type="checkbox"/>	L4	L3 same diameter	80
<input checked="" type="checkbox"/>	L3	L1 same mns same cus	2569
<input checked="" type="checkbox"/>	L2	L1 same shadow same mask	5
<input checked="" type="checkbox"/>	L1	(iron or fe) same (ni or nickel) same (cu or copper) same (mn or manganese) same (s or sulfur)	2627

END OF SEARCH HISTORY